

There is strong AM interference here starting around 1650 continuously to 25000+. It is a regular, powerful clicking or ticking noise, about 2 times per second. It gets louder as I raise the gain. The signal nulls somewhat when the radio (facing me) is pointed south.